

TEST REPORT

Number: GZHT02194297

Applicant: GUANGZHOU MOS TRADING CO.,LIMITED
NO.175, SHINAN RD,DONGCHONG TOWN
NANSHA DISTRICT, GUANGZHOU GUANGDONG
CHINA


Date: Sep 17, 2019

Attn: 施文涛

Sample Description As Declared :

No. Of Sample : One
Fibre Content : 100% Solution-Dyed
Material : 100% Olefin Woven fabric
Finishing : -
End Uses : Cushion, pillow
Season : -
Colour : Green
Style No. : 15260402(402.202)
Order No./PO No. : -
Buyer's Name : -
Manufacturer's Name : -
Ref. : -

Prepared And Checked By:
For Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch



Lin Lin
General Manager

se / jessiezhou



Page 1 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch

3/F, Hengyun Building, 235 Kaifa Ave., Guangzhou
Economic & Technological Development District, Guangzhou, China

深圳天祥质量技术服务有限公司广州开发区分公司

中国广州经济技术开发区开发大道 235 号恒运大厦 3 楼

Tel: +86 20 8396 6868 Fax: +86 20 8222 8169 Postcode:510730

www.intertek.com

TEST REPORT

Number: GZHT02194297

Applicant's Provided Care Instruction/Label :

Machine Wash Cold
Permanent Press Cycle
Line Dry
Do Not Iron
Chlorine Bleach If Needed

Date Received/Date Test Started : Sep 06, 2019/Sep 09, 2019


Date Final Information Confirmed: -

Conclusion:

Based upon the results of flammability test reported, the sample submitted for testing meets the flammability requirements of the Canada's Textile Flammability Regulations (SOR/2016-194).

Prepared And Checked By:

For Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch



Lin Lin
General Manager

se / jessiezhou



Page 2 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch

3/F, Hengyun Building, 235 Kaifa Ave., Guangzhou
Economic & Technological Development District, Guangzhou, China

深圳天祥质量技术服务有限公司广州开发区分公司

中国广州经济技术开发区开发大道 235 号恒运大厦 3 楼

Tel: +86 20 8396 6868 Fax: +86 20 8222 8169 Postcode:510730

www.intertek.com

TEST REPORT

Number: GZHT02194297

Tests Conducted (As Requested By The Applicant)

1 Flammability Test - Textiles Flammability Regulations (SOR/2016-194) (CAN/CGSB-4.2 No.27.5-2008):

The Apparatus And Methods Of Testing Were Those Described In Canadian General Standard Board Textile Test Method CAN/CGSB-4.2 No.27.5-2008

<u>Original</u>		<u>After Drycleaning And Washing#</u>		<u>Requirement</u>
DNI	DNI	DNI	DNI	Plain Surface
DNI	DNI	DNI	DNI	> 3.5 seconds
DNI	DNI	DNI	DNI	Raised Fibre Surface
DNI	DNI	DNI	DNI	> 4.0 seconds
DNI	DNI	DNI	DNI	

Remark : DNI = Did not ignite.

Cleansing Condition : The sample was first undergone commercial drycleaning in perchloroethylene and then washed accordance with CAN/CGSB-4.2 No. 58, Machine Wash At 30°C, Permanent Press Cycle, Followed By Line Dry.

End of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report(except for full text copy) shall be made without the written approval by Intertek.

se / jessiezhou

Page 3 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch

3/F, Hengyun Building, 235 Kaifa Ave., Guangzhou

Economic & Technological Development District, Guangzhou, China

深圳天祥质量技术服务有限公司广州开发区分公司

中国广州经济技术开发区开发大道 235 号恒运大厦 3 楼

Tel: +86 20 8396 6868 Fax: +86 20 8222 8169 Postcode:510730

www.intertek.com